



OIL & NATURAL GAS COMMISSION (B.O.P.) KARMACHARI SANGHATANA

AFFILIATED TO - PETROLIUM & GAS WORKERS' FEDERATION OF INDIA

Reg. No. (By - II - 8268)

Tel. : 2659 9775

Flat No.102, 1st Floor, Acme Harmony-I, Poonam Nagar, Off. JV Link Road, Andheri (E), Mumbai - 400 093.

REF. : ONGC/KS/288/2015

DATE : 22/06/2015

To,
The GGM-HDS,
ONGC - WOU,
11 high, Sion-Bandra Link Rd.,
Sion, Mumbai 400017.

O/C

Subject : Repairing and procurement of equipments on Rig S/Kiran.

Respected Sir,

We are in receipt of complaints from crew of the Sagar Kiran regarding nonworking of drilling equipments on Rig Sagar Kiran. Following are the complaints for which immediate action is required for repair and/or to procure the equipments.

- Winches on rig floor are jammed and NDT of the winch ropes has not been done from last 1½ years. As per periodical maintenance NDT should be done every after 3 months.
- Pulleys associated with winch are not in safe condition, these pulleys are to be changed but it is told that proposal has been initiated but after laps of one year no progress is seen.
- BOP winch use to fit or remove BOP is in very bad condition. Pulleys of the winch block are out of order. Only one bearing of one block has been changed but the bearing replaced is not original. As you are aware the weight of the BOP is more than 15 tones, fatal accident can take place anytime on the rig.
- 6½" and 8" slips are not available on Rig Floor.
- Elevators used for tubing and for 5" drill pipes are not proper in size.

Pass


ONGC
Office of I/C HR/ER
Services DIARY No. 22/6/15
In _____ Date _____
Out _____ Date _____

:: 2 ::

- Spanners to remove the piston from mud pump are not standard in size, therefore work suffers & it takes more time to complete the job.
- No Nut & Bolt of proper size are available on Rig.
- Wooden Floor on Rig Floor, where pipes are kept is fully decayed.

All above issues mentioned are related to safety and productivity. Your esteemed authority is requested to look into the matter and kindly direct the concern officer to take preventing action and to initiate the action for procurement of required equipments.

Thanking you,
Yours faithfully,


(Pradeep Mayekar)
General Secretary

O/C

Copy to:

1. LMDS, ONGC-WOU, 11 high, Sion-Bandra link Rd, Sion, M'bai 17.
2. Rig Manager, S/Kiran, ONGC-WOU, 11 high, Sion, Mumbai 17.
3. DGM, I/c HR-ER, Services, ONGC-WOU, 11 high, Sion, Mumbai 17.
4. CM (HR)IR, ONGC-WOU, Green Height, BKC, Bandra (E), M'bai 51.

Debate
23/6/15

23/6/15
20000