



OIL & NATURAL GAS COMMISSION (W.O.U.) KARMACHARI SANGHATANA

AFFILIATED TO - PETROLIUM & GAS WORKERS' FEDERATION OF INDIA

Reg. No. (By - II - 8268)

Tel. : 2659 9775

Flat No.102, 1st Floor, Acme Harmony-I, Poonam Nagar, Off. JV Link Road, Andheri (E), Mumbai - 400 093.

REF. : ONGC/KS/105 /20 16

DATE : 30/08/2016

To, CDS-DW
The ED - ~~HDW~~
ONGC, WOU,
11 High, Sion-Bandra Link Rd.,
Sion,
Mumbai : 400 017.

o/c

Subject : Perennial AC problem of Rig Sagar Vijay.

Respected Sir,

Please find enclosed a copy of complaint by Crew members of Rig Sagar Vijay on the above issue.

Due to inappropriate compatibility of the new compressor installed faces frequent shutdown, needing maintenance and non availability of a parallel compressor continuous AC is not available in the living room resultant discomfort and its health & performance repercussion needs no elaboration.

Your esteemed authority is requested to the needful at the earliest least patience runs over and repulsion activities surfaces.

Thanking you,
Yours faithfully,

o/c

Pradeep
(Pradeep Mayekar)
General Secretary

Copy to:

1. GM - LMDS, Deep Water, ONGC, 11 High, Sion-Bandra Lk Rd. Mum:17.
2. Rig Manager Sagar Vijay, ONGC, 11 High, Sion-Bandra Lk Rd. Mum : 17.
3. DGM, I/c, HR/ER, Services, ONGC, 11 High, Sion Mum : 17.
4. DGM, I/c, IR, ONGC-WOU, Gr. Heights, BKC, Bandra (E), Mum: 51.

Aswani
31/8/16

Pradeep
31/8/16

To,
The OIM,
Sagar Vijay
Mumbai.

Date - 21 Aug. 2016

Sub:- Long pending AC problem at rig Sagar Vijay.

This is to bring to your kind attention that ongoing problem regarding air conditioning system at rig Sagar Vijay. The earlier AHU system was replaced at current SKL Dry-dock, but only one compressor was changed. The system is currently working on only one Compressor with no stand-by/backup option for it. If any shut down happens/compressor taken for offload for maintenance, there is no any stand by option.

As promised by the management, the new compressor will come while we are at high seas, but as per our earlier experience, the starboard side bulk has to be cut for taking compressor inside of the AC Room, which is not possible while we are at sea.

It is hereby requested to ensure that air conditioning system of rig made fully operational with requisite stand by before the ship commences sailing from Kakinada Port.

In the absence of system, the accommodation becomes inhospitable leading to severe physical and mental trauma of the employees.

- 1) A. M. BAGWE. - Abagwe
- 2) R G Rawal - Rawal
- 3) D.I. Chalise - Dhalise
- 4) J. P. KARIA - J.P.
- 5) Prafull Bandarkar - Pruf
- 6) Laxman Anandhujgaonkar - Shyde
- 7) S. T. PARGARE - Shy
- 8) V. S. Patil - Patil
- 9) Vikram Babhulkar - V.B.
- 10) Vinay Nyare - Nyare
- 11) Jaydeb Redkar - Redkar
- 12) Dilipk. Dohare - Dohare
- 13) Vijay B. Asukar - Asukar
- 14) Abrar Ahmed - Abrar
- 15) Shyam A. Patil - Shyam
- 16) Karilash Dawarne - Dawarne
- 17) Saurabh S. Sommathe - Sommathe

C.C.

1. The General Secretary,
ONGC BOP Karmachari Sanghathna,
Mumbai.

Received
on 22/8/16, 1050hrs.
75
22/8/16
K. T. K. K.
Dy. General Manager (D)
OIM, SAGAR VIJAY,
ONGC.